

23 STATE STREET OSSINING, NEW YORK 10562 TEL.: (914) 762-6333 FAX: (914) 762-5578

WWW.EMSOFNY.COM

December 13 of 2014

Environmental Science

TD Development 720 Eagle View Ct Mason, OH 45040

Safety Engineering

Attn: Todd Clifford

Ref: Site Contamination Assessment for Buildings #73 & #74 Warehouse's at Beechnut Canj. NY

Industrial Hygiene On December 13 of 2014, an asbestos visual inspection for **Buildings #73 & #74, Warehouse's roofs at Beechnut Canj. NY** performed by Brian K. McLaren a AHERA/NYS inspector and NYS/EPA Designer.

Environmental and Occupational Health No Asbestos containing building materials were found, the roofs were of metal & rubber construction for both roofs, concrete slab on grade, #73 was brick wall construction, # 74 was metal wall construction, no bulk samples were collected.

Non-Asbestos containing building materials within the building which were not tested as per 40 CFR 763 & 12NYCRR Part 56.

Medical Ecology Glass Metal

Other Mechanical/Building Components Brick, Granite, Marble, or other stonework

Wood or Wood composite materials Concrete or mortar

Rubber or synthetic materials Foam or synthetic materials

Pink/Yellow Fiber Glass Insulation Clay/Ceramic Tiles

Plastic/Vinyl materials Carpeting, curtains, wall paper or other synthetic

Hazardous Materials Management

Any product manufactured with in the USA after 1980

Certification of Assessment

Brian K. McLaren

materials

As the AHERA/NYSDOL Certified - Inspector/Management Planner & Designer Certification: AH#88-10819 responsible for the development of this assessment for building Materials for the Buildings #73 & #74 Warehouse's at Beechnut Canj. NY. This has been written and reviewed in a manner along with letters and other written materials from the manufactory who supplied these materials, which is in full compliance with the applicable rules and regulations as required by PART 56 of Title 12 NYCRR and Federal Regulations 40 CFR, Part 763. Should you have any questions, please contact us at (518) 453-3400.

Testing

Laboratory

Environmental Health and Safety Training

> Brian K. McLaren Inspector

Emergency Response Services

Remediation and Restoration Services